



46980 State Highway M26
P.O. Box 309
Houghton, MI 49931
www.somero.com
(906) 482-7252

July 11, 2005

Somero Equipment Owner

Dear Valued Customer,

It has come to our attention that your Somero SXP™ Laser Screed® machines (Serial Number Range 30000 to 30092) have been shipped with an incorrect identification label for the main hydraulic manifold on the lower frame. Also related to this error, the hydraulic schematic in your manual, page D.2.2, has an error. We ask that you replace that page with the new one supplied in this notice.

The label we've mentioned is located on the inside of the lower frame removable manifold cover, next to the fuel tank. Included is a picture of the location of the label for reference.

We ask that you simply clean the old label very well and apply the new label directly over it in order to correct this problem. You will find the new label included with this notice.

We apologize for any inconvenience this may have caused you and your crews, but we are happy we were able to detect the problem and correct it.

If you have any questions, please feel free to contact our customer support department at (906) 482-7252 Option 4 and one of our agents will assist you.

Sincerely,

Darrin Luukkonen
Customer Support Representative
Somero Enterprises
Phone: 906-482-7252 option 4
Fax: 906-483-2774
E-mail: support@somero.com