



46980 State Highway M26
P.O. Box 309
Houghton, MI 49931
www.somero.com
(906) 482-7252 Option 4

July 26, 2005

Somero Equipment Owner

**IMPORTANT NOTICE
For SXP Laser Screed Owners
SXP Serial #30000-30092
Equipped With Catalytic
Mufflers**

Dear Valued Customer –

Thank you for putting your trust in Somero Enterprises. To ensure highly reliable machine operation, customer feedback is monitored continuously and quality concerns are addressed immediately once identified.

On several machines equipped with catalytic mufflers, premature failure of the fan has occurred. In these cases, the cooling fan has made contact with the fan shroud. This problem appears to be caused by the radiator assembly coming loose and machine vibration causing these parts to come in contact.

In order to prevent this from happening to your equipment, the fan shroud and bracket assembly has been redesigned. Parts are in stock to replace the components on your machine immediately.

Through our partnership with Cummins NPower, the Cummins distributor and dealer network will facilitate the repairs.

The repairs should take less than 2 hours to perform, and can fit in around your busy summer schedule. Please contact Bob Janquart by **September 1, 2005** to coordinate a repair schedule.

Key Information	
Cummins NPower Contact	Bob Janquart (800) 236-9750 x 5917 (920) 362-0865 Cell Bob.G.Janquart@Cummins.com
Machine Serial Number	Somero SXP Laser Screeds 30000-30092 With Catalytic Mufflers
Campaign Reference	"Fan Shroud & Bracket Update"

If you have any questions or concerns do not hesitate to call our customer support department at 906.482.7252 Option 4.



Thank you for your patience and understanding.

Respectfully yours,

Jim Desrochers
Director of Customer Support